

## **CONSTRUCTION OBSERVATION REPORT #7**

**Date:** October 10, 2016

**Project Title:** Arizona Way Bridge Construction Project

**Record by:** Blake Lettenmaier, PE, PLS

**Project #:** PW 2016-100

**Contractor:** KSH Construction Co.

**Location:** T 1N, R 10, SECTION 22, BA, Willamette  
Meridian, Tillamook County, OR

### **Weather Conditions**

Sunny

Temperature: 52 deg. F

Wind: 0-6 mph

### **Soil surface Condition**

Moist

### **Summary**

Contractor is preparing to divert stream by pumping around. Stream diversion accomplished. Stream turbidity monitoring yields the same visual turbidity (clear) at both compliance locations. Straw mulch, silt fencing, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.









Stream turbidity comparisons at compliance locations



Stream turbidity comparisons at compliance locations

END



Renews: 12-31-2016

c: *City of Garibaldi Staff*  
*File*