



City Hall, PO Box 708, Garibaldi, OR 97118
Office: (503) 322-3327 | Fax: (503) 322-3737
City Manager email: john@ci.garibaldi.or.us

CONSTRUCTION OBSERVATION REPORT #9

Date: October 12, 2016

Project Title: Arizona Way Bridge Construction Project

Record by: Blake Lettenmaier, PE, PLS

Project #: PW 2016-100

Contractor: KSH Construction Co.

Location: T 1N, R 10, SECTION 22, BA, Willamette Meridian, Tillamook County, OR

Weather Conditions

Sunny

Temperature: 65 deg. F

Wind: 0-6 mph

Soil surface Condition

Moist

Summary

Contractor is placing additional erosion control measures in preparation of forecasted rains. Contractor is placing fabric and crushed rock on temporary access road. Contractor is potholing underground utilities and starting to excavate for sanitary manhole installation. Stream turbidity monitoring yields the same visual turbidity (clear) at both compliance locations. Straw waddle, Straw check dams, straw mulch, silt fencing, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.







































Stream turbidity comparisons at compliance locations



Stream turbidity comparisons at compliance locations

END



Renews: 12-31-2016

c: *City of Garibaldi Staff*
File