

CONSTRUCTION OBSERVATION REPORT #13

Date: October 18, 2016

Project Title: Arizona Way Bridge Construction Project

Record by: Blake Lettenmaier, PE, PLS

Project #: PW 2016-100

Contractor: KSH Construction Co.

Location: T 1N, R 10, SECTION 22, BA, Willamette Meridian,
Tillamook County, OR

Weather Conditions

Partly cloudy

Temperature: 63 deg. F

Wind: 0-10 mph

Soil surface Condition

Moist

Summary

Contractor is installing sanitary sewer manhole and line to lift station and reinstalling storm line supplied by city as they go. Stream turbidity monitoring yields slightly more turbidity at the downstream compliance location (less than 10% increase). See compliance comparisons below. Straw waddle, straw check dams, straw mulch, silt fencing, bio bags, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.







Stream turbidity comparisons at compliance locations



Stream turbidity comparisons at compliance locations



Stream turbidity comparisons at compliance locations

END



Renews: 12-31-2016

c: City of Garibaldi Staff
File