City Hall, PO Box 708, Garibaldi, OR 97118
Office: (503) 322-3327 | Fax: (503) 322-3737
City Manager email: john@ci.garibaldi.or.us

CONSTRUCTION OBSERVATION REPORT #19

Date: October 26, 2016

Project Title: Arizona Way Bridge Construction Project

Record by: Blake Lettenmaier, PE, PLS

Project #: PW 2016-100

Contractor: KSH Construction Co.

Location: T 1N, R 10, SECTION 22, BA, Willamette Meridian, Tillamook County, OR

Weather Conditions

Overcast

Temperature: 58 deg. F

Wind: 0-15 mph

Soil surface Condition

Moist

Summary

Contractor is installing last leg of sewer pipe and connecting to the lift station. Stream turbidity monitoring yielded turbidity levels with less than 10% increase at the downstream compliance location. See compliance comparisons below. Straw waddles, straw check dams, straw mulch, silt fencing, bio bags, sand bags, sediment ponds, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.

10/26/2016 12:24
10/26/2016 12:26
10/26/2016 12:32
10/26/2016 13:20
10/26/2016 14:29
10/26/2016 14:36

Arizona Way
ROAD CLOSED
10/26/2016 14:41

10/26/2016 14:42

#7 PUMP STATION
10/26/2016 14:47

10/26/2016 14:47

10/26/2016 14:54

10/26/2016 15:11

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

END

Renews: 12-31-2016

c: *City of Garibaldi Staff*
File