City Hall, PO Box 708, Garibaldi, OR 97118
Office: (541) 201-8154 | Fax: (503) 616-7912
City Engineer email: blake@ci.garibaldi.or.us

CONSTRUCTION OBSERVATION REPORT #31

Date: November 21, 2016

Project Title: Arizona Way Bridge Construction Project

Record by: Blake Lettenmaier, PE, PLS

Project #: PW 2016-100

Contractor: KSH Construction Co.

Location: T 1N, R 10, SECTION 22, BA, Willamette Meridian, Tillamook County, OR

Weather Conditions

Sunny

Temperature: 56 deg. F

Wind: 0-10 mph

Soil surface Condition

Moist

Summary

Contractor is installing the bridge. Stream turbidity monitoring yielded turbidity levels less than 10% increase at the downstream compliance location. See compliance comparisons below. Straw waddles, straw check dams, straw mulch, silt fencing, bio bags, sand bags, sediment ponds, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.

11/21/2016 14:13
11/21/2016 15:26
11/21/2016 15:31
ROAD
CLOSED
11/21/2016 15:59
11/21/2016 15:59
11/21/2016 16:00

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

Stream turbidity comparisons at compliance locations

END

Renews: 12-31-2016

c: *City of Garibaldi Staff*
File